


















 MT x16	 M x16	 7x50 WK5 x16	 8x30 D8 x2	 3.5x13 W3513 x36	 3.5x16 W3516 x1	 A02 x30
 A06 x1	 A05 x1	 PK x6		 S2 x4	 3.5x30 WS x8	
 A01 x1						




I






III




IV




V




VI




VII





VIII




IX



X



XI



XII

